

Rehabilitation Register – McArthur River Project Area, June 2019



Rehabilitation Status

Summarise the rehabilitation status of all exploration sites during the current and previous reporting periods.

Exploration Activities Rehabilitation Summary (Cumulative)											
Reporting period	Tenement	MMP Reference	Drill Holes /Pads (No.)	Rehab'd Drill Holes/ Pads (No.)	Drill Line/ Access Track Length (km)	Rehab'd drill line/access track (km)	Camp (ha)	Camp Rehab'd (ha)	Costeans /Bulk Samples (No.)	Costeans /Bulk Samples rehab'd (No.)	Comments
01/07/15-30/06/16	EL27711	Auth. 0805-01	1	1	3.3		0.09	0.09	NA	NA	Windrows and dirt piles along access tracks have been flattened. Areas of minor erosion have been remediated and creek crossing recontoured. Tracks are not going to be ripped at this stage but will be allowed to revegetate.
01/07/15-30/06/16	EL30085	Auth. 0805-01	1	1	3.9		NA	NA	NA	NA	Windrows and dirt piles along access tracks have been flattened. Areas of minor erosion have been remediated. Tracks are not going to be ripped at this stage but will be allowed to revegetate.
01/07/16-30/06/17	EL27711	Auth. 0805-01	1	1	3.3		0.09	0.09	NA	NA	Rehabilitation progressing well.
01/07/16-30/06/17	EL30085	Auth. 0805-01	1	1	3.6		NA	NA	NA	NA	Rehabilitation progressing well.
01/07/17-30/06/18	EL27711	Auth. 0938-01	1	1	3.3		0.09	0.09	NA	NA	Rehabilitation progressing well.
01/07/17-30/06/18	EL30085	Auth. 0938-01	1	1	3.6		NA	NA	NA	NA	Rehabilitation progressing well.
01/07/18-30/06/19	EL27711	Auth. 0938-01	3	3	9		0.09	0.09	NA	NA	Previous sites, revegetation progressing well. New sites, rehab completed, monitoring will now take place.
01/07/18-30/06/19	EL30085	Auth. 0938-01	2	2	7.27		NA	NA	NA	NA	Previous sites, revegetation progressing well. New sites, rehab completed, monitoring will now take place.

Provide details (where applicable) of the rehabilitation activities that were conducted during the past 12 months and from previous reporting periods.

Drill Hole/Pad Rehabilitation Status												
Tenement	Drill Hole ID	Easting (GDA 94 Zone 53)	Northing (GDA 94 Zone 53)	MMP Reference	Date Drilled	Drilling Method*	Size of Drill Pad (m ²)	No. of sumps	Status [†]	Rehab Date	Planned Rehab Date	Comments
EL27711	MCDD0001	597375	8112575	Auth. 0805-01	14/09/14	D	300	2	C	May 2016		Added as a monitoring site. Will be photographed annually and remediated as necessary.
EL30085	MCDD0002	594575	8108475	Auth. 0805-01	23/09/14	D	300	2	C	May 2016		Added as a monitoring site. Will be photographed annually and remediated as necessary.
EL30085	MCDD0003	591370	8106448	Auth. 0938-01	14/08/18	D	300	2	C	June 2019		Added as a monitoring site. Will be photographed annually and remediated as necessary.
EL27711	MCDD0004	599252	8110618	Auth. 0938-01	26/08/18	D	300	2	C	June 2019		
EL27711	MCDD0005	599179	8113578	Auth. 0938-01	3/09/18	D	300	2	C	June 2019		

* AC = aircore/vacuum, RM = rotary mud, RC = reverse circulation, RAB = rotary air blast, D = diamond, P = percussion, V = vibracore or sonic, O = other.

† C = drillsite completely rehabilitated (hole collar removed plugged and backfilled, drill spoils buried and sample bags removed, sumps backfilled, drill pads re-contoured and ripped, photograph taken), N = no rehabilitation completed, PR = partial rehabilitation (specify remaining rehabilitation to be completed within the comments section).

Access Track/Drill Line Rehabilitation Status

Tenement	Track ID	Tracks/lines Created (km)	Rehab'd tracks/lines (km)	Status [†]	Rehab Date	Planned Rehab Date	Comments
EL27711		3.3		PR	May 2016		Windrows and dirt piles along access tracks have been flattened. Areas of minor erosion noted in 2016 were remediated and creek crossing recontoured. Tracks have not been ripped but will be allowed to revegetate naturally. The length of the track will also be inspected annually and remediated as necessary.
EL30085		3.6		PR	May 2016		Windrows and dirt piles along access tracks have been flattened. Areas of minor erosion noted in 2016 were remediated. Tracks have not been ripped but will be allowed to revegetate naturally. A point along the track has been included as a monitoring site and the length of the track will also be inspected annually and remediated as necessary.
EL27711		5.7		PR	June 2019		Tracks have not been ripped but will be allowed to revegetate naturally. A monitoring site has been added at the corner heading east towards MCDD0004. The length of the track will also be inspected annually and remediated as necessary.
EL30085		3.67		PR	June 2019		Tracks have not been ripped but will be allowed to revegetate naturally. The length of the track will also be inspected annually and remediated as necessary.

[†] C = rehabilitation completed, N = no rehabilitation completed, PR = partial rehabilitation (specify remaining rehabilitation to be completed within the comments section).

Campsite Rehabilitation Status

Tenement	Camp Name	Date Est.	Easting (GDA 94 Zone 53)	Northing (GDA 94 Zone 53)	Camp Size (ha)	Status [†]	Waste Removed	Camp Rehab Date	Planned Rehab Date	Comments
EL27711	Drillers Camp	12/09/14	596411	8110322	0.09	C	YES	May 2016		Added as a monitoring site. Will be photographed annually and remediated as necessary.
EL27711	Drillers Camp	12/09/14	596411	8110322	0.09	C	YES	June 2019		Reused for 2018 drilling. Currently a monitoring site. Will be photographed annually and remediated as necessary.

[†] C = rehabilitation completed, N = no rehabilitation completed, PR = partial rehabilitation (specify remaining rehabilitation to be completed within the comments section).