



Provide details (where applicable) of the rehabilitation activities that were conducted during the past 12 months and from previous reporting periods.

Drill Hole/Pad Rehabilitation Status												
Tenement	Drill Hole ID	Easting (GDA 94 Zone 53)	Northing (GDA 94 Zone 53)	MMP Reference	Date Drilled	Drilling Method*	Size of Drill Pad (m <sup>2</sup> )	No. of sumps	Status <sup>†</sup>	Rehab Date	Planned Rehab Date	Comments
EL27892	MHRC0001	761948	7552979	Authorisation 0709-01	Nov 2012	RC	300*		C	Complete – October 2015		*Same pad used for 12MHRC007 and 13MHDDH010
EL27892	MHRC0002	765050	7554048	Authorisation 0709-01	Nov 2012	RC	300*		C	Complete – October 2015		*Same pad used for 13MHDDH014
EL27892	MHRC0003	764151	7551401	Authorisation 0709-01	Nov 2012	RC	300*		C	Complete – October 2015		*Same pad used for 13MHDDH013
EL27892	MHRC0004	764700	7550509	Authorisation 0709-01	Nov 2012	RC	300		C	Complete – October 2015		
EL27892	MHRC0005	762048	7552851	Authorisation 0709-01	Nov 2012	RC	300		C	Complete – October 2015		
EL27892	MHRC0006	765050	7554053	Authorisation 0709-01	Nov 2012	RC	300*		C	Complete – October 2015		*Same pad used for 13MHDDH012
EL27892	MHRC0007	761939	7552981	Authorisation 0709-01	Nov 2012	RC	300*		C	Complete – October 2015		*Same pad used for 12MHRC001 and 13MHDDH010
EL27892	MHDD0001	766432	7552941	Authorisation 0709-01	March 2013	D	300	1	C	Complete – October 2015		
EL27892	MHDD0002	766405	7553004	Authorisation 0709-01	March 2013	D	300	1	C	Complete – October 2015		
EL27892	MHDD0003	766483	7552968	Authorisation 0709-01	March 2013	D	300	1	C	Complete – October 2015		
EL27892	MHDD0004	766536	7553017	Authorisation 0709-01	March 2013	D	300	1	C	Complete – October 2015		
EL27892	MHDD0005	760866	7554801	Authorisation 0709-01	March 2013	D	300*	1*	C	Complete – October 2015		*Same pad and sump used for 13MHDDH005, 006 and 007.
EL27892	MHDD0006	760866	7554801	Authorisation 0709-01	March 2013	D	300*	1*	C	Complete – October 2015		*Same pad and sump used for 13MHDDH005, 006 and 007.
EL27892	MHDD0007	760866	7554801	Authorisation 0709-01	March 2013	D	300*	1*	C	Complete – October 2015		*Same pad and sump used for 13MHDDH005, 006 and 007.

**Drill Hole/Pad Rehabilitation Status**

Tenement	Drill Hole ID	Easting (GDA 94 Zone 53)	Northing (GDA 94 Zone 53)	MMP Reference	Date Drilled	Drilling Method*	Size of Drill Pad (m <sup>2</sup> )	No. of sumps	Status <sup>†</sup>	Rehab Date	Planned Rehab Date	Comments
EL27892	MHDD0008	760886	7554706	Authorisation 0709-01	March 2013	D	300*	1*	C	Complete – October 2015		*Same pad and sump used for 13MHDDH008 and 009.
EL27892	MHDD0009	760886	7554706	Authorisation 0709-01	March 2013	D	300*	1*	C	Complete – October 2015		*Same pad and sump used for 13MHDDH008 and 009.
EL27892	MHDD0010	761943	7552979	Authorisation 0709-01	March 2013	D	300*	1*	C	Complete – October 2015		*Same pad used for 12MHRC001 and 12MHRC007
EL27892	MHDD0011	761849	7553098	Authorisation 0709-01	March 2013	D	300	1	C	Complete – October 2015		
EL27892	MHDD0012	765050	7554050	Authorisation 0709-01	March 2013	D	300*	1	C	Complete – October 2015		*Same pad used for 12MHRC006
EL27892	MHDD0013	764177	7551451	Authorisation 0709-01	March 2013	D	300*	1	C	Complete – October 2015		*Same pad used for 12MHRC003
EL27892	MHDD0014	766238	7552929	Authorisation 0709-01	March 2013	D	300*	1	C	Complete – October 2015		*Same pad used for 12MHRC002
EL27892	MHDD0015	760902	7554549	Authorisation 0709-01	March 2013	D	300	1	C	Complete – October 2015		
EL27892	MHRC0016	760900	7554510	Authorisation 0923-01	Apr 2017	RC	300		C	Complete – October 2017		
EL27892	MHRC0017	760897	7554601	Authorisation 0923-01	Apr 2017	RC	300		C	Complete – October 2017		
EL27892	MHRC0018	761008	7554510	Authorisation 0923-01	Apr 2017	RC	300		C	Complete – October 2017		
EL27892	MHRC0019	760815	7554602	Authorisation 0923-01	Apr 2017	RC	300		C	Complete – October 2017		
EL27892	MHRC0020	766180	7552906	Authorisation 0923-01	Apr 2017	RC	300		C	Complete – October 2017		
EL27892	MHRC0024	764928	7554057	Authorisation 0923-01	Apr 2017	RC	300*		C	Complete – October 2017		* Same drillpad as MHDD0023 and 0029
EL27892	MHRC0026	766364	7552942	Authorisation 0923-01	June 2017	RC	300		C	Complete – October 2017		

**Drill Hole/Pad Rehabilitation Status**

Tenement	Drill Hole ID	Easting (GDA 94 Zone 53)	Northing (GDA 94 Zone 53)	MMP Reference	Date Drilled	Drilling Method*	Size of Drill Pad (m <sup>2</sup> )	No. of sumps	Status <sup>†</sup>	Rehab Date	Planned Rehab Date	Comments
EL27892	MHRC0027	766400	7552945	Authorisation 0923-01	June 2017	RC	300		C	Complete – October 2017		
EL27892	MHRC0028	766185	7552860	Authorisation 0923-01	June 2017	RC	300		C	Complete – October 2017		
EL27892	MHDD0021	761924	7552975	Authorisation 0923-01	April/May 2017	RC/D	300	1	C	Complete – October 2017		
EL27892	MHDD0022	761753	7553150	Authorisation 0923-01	April/May 2017	RC/D	300	1	C	Complete – October 2017		
EL27892	MHDD0023	764936	7554051	Authorisation 0923-01	April/ June 2017	RC/D	300*	1	C	Complete – October 2017		* Same drillpad as 17MHRC024 and 17MHRCDDH029
EL27892	MHDD0025	761857	7553052	Authorisation 0923-01	May 2017	RC/D	300	1	C	Complete – October 2017		
EL27892	MHDD0029	764930	7554056	Authorisation 0923-01	June 2017	RC/D	300*	1	C	Complete – October 2017		* Same drillpad as 17MHRC024 and 17MHRCDDH023.
EL27892	MHDD0030	761940	7552963	Authorisation 0923-01	May 2018	RC/D	300*	1	C	November-December 2018		
EL27892	MHDD0031	761930	7552912	Authorisation 0923-01	May/June 2018	RC/D	300	1	C	November-December 2018		
EL27892	MHDD0032	761923	7553003	Authorisation 0923-01	May 2018	RC/D	300	1	C	March 2019		
EL27892	MHDD0033	764995	7554083	Authorisation 0923-01	May 2018	RC/D	300	1	C	March 2019		
EL27892	MHDD0034	761930	7552925	Authorisation 0923-01	June 2018	RC/D	300	1	C	March 2019		
EL27892	MHDD0021A	761923	7552974	Authorisation 0923-01	June 2018	RC/D	300*	1*	C	March 2019		
EL27892	MHDDH0035	761946	7552867	Authorisation 0923-01	June 2018	RC/D	300	1	C	March 2019		

**Drill Hole/Pad Rehabilitation Status**

Tenement	Drill Hole ID	Easting (GDA 94 Zone 53)	Northing (GDA 94 Zone 53)	MMP Reference	Date Drilled	Drilling Method*	Size of Drill Pad (m <sup>2</sup> )	No. of sumps	Status <sup>†</sup>	Rehab Date	Planned Rehab Date	Comments
EL27892	MHDDH0037	761956	7552834	Authorisation 0923-01	June 2018	RC/D	300	1	C	March 2019		
EL27892	MHDDH0038	761924	7552977	Authorisation 0923-01	June 2018	RC/D	300	1	C	March 2019		
EL27892	MHDDH0039	761925	7552970	Authorisation 0923-01	July 2018	RC/D	300	1	C	March 2019		
EL27892	MHDDH0040	762064	7552875	Authorisation 0923-01	July 2018	RC/D	300	1	C	March 2019		
EL27892	MHDDH0041	761892	7553037	Authorisation 0923-01	Oct/Nov 2018	RC/D	400*	1	PR		Nov 2019	Shared with MHDD0042. Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0042	761888	7553039	Authorisation 0923-01	Oct/Nov 2018	RC/D	400*	1	PR		Nov 2019	Shared with MHDD0041. Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0043	761921	7553066	Authorisation 0923-01	Oct/Nov 2018	RC/D	400*	1	PR		Nov 2019	Shared with MHDD0052. Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0044	761900	7552985	Authorisation 0923-01	Oct/Nov 2018	RC/D	400*	1	PR		Nov 2019	Shared with MHDD0045 and 0047. Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0045	761894	7552991	Authorisation 0923-01	Nov 2018	RC/D	400*	1	PR		Nov 2019	Shared with MHDD0044 and 0047. Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0046	761902	7552941	Authorisation 0923-01	Nov/Dec 2018	RC/D	300	1	PR		Nov 2019	Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0047	761908	7552983	Authorisation 0923-01	Nov/Dec 2018	RC/D	400*	1	PR		Nov 2019	Shared with MHDD0044 and 0045. Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0048	762072	7553090	Authorisation 0923-01	Dec 2018	RC	300	1	PR		Nov 2019	Collar still to be cut below ground. Site safe, clean and tidy.

**Drill Hole/Pad Rehabilitation Status**

Tenement	Drill Hole ID	Easting (GDA 94 Zone 53)	Northing (GDA 94 Zone 53)	MMP Reference	Date Drilled	Drilling Method*	Size of Drill Pad (m <sup>2</sup> )	No. of sumps	Status <sup>†</sup>	Rehab Date	Planned Rehab Date	Comments
EL27892	MHDDH0049	762077	7552982	Authorisation 0923-01	Dec 2018	RC	300	1	PR		Nov 2019	Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0050	762088	7552932	Authorisation 0923-01	Dec 2018	RC	300	1	PR		Nov 2019	Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0051	762064	7552945	Authorisation 0923-01	Dec 2018	RC	300	1	PR		Nov 2019	Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0052	761922	7553061	Authorisation 0923-01	Dec 2018	RC/D	400	1	PR		Nov 2019	Shared with MHDD0043. Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0053	761889	7553008	Authorisation 0923-01	March 2019	RC	600	1	PR		Nov 2019	Shared with 53A, 54, 56 and 57. Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0053a	761887	7553009	Authorisation 0923-01	March 2019	RC/D	600	1	PR		Nov 2019	Shared with 53, 54, 56 and 57. Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0054	761893	7553005	Authorisation 0923-01	March 2019	RC	600	1	PR		Nov 2019	Shared with 53, 53A, 56 and 57. Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0055	761852	7553135	Authorisation 0923-01	March 2019	RC/D	300	3	PR		Nov 2019	Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0056	761879	7553021	Authorisation 0923-01	April 2019	RC/D	600	1	PR		Nov 2019	Shared with 53, 53A, 54 and 57. Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0057	761884	7553019	Authorisation 0923-01	April 2019	RC/D	600	1	PR		Nov 2019	Shared with 53, 53A, 54 and 56. Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0058	761858	7553162	Authorisation 0923-01	April 2019	RC/D	300	1	PR		Nov 2019	Shared with MHDD0060. Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0059	761903	7552939	Authorisation 0923-01	April 2019	RC/D	300	2	PR		Nov 2019	Collar still to be cut below ground. Site safe, clean and tidy.

**Drill Hole/Pad Rehabilitation Status**

Tenement	Drill Hole ID	Easting (GDA 94 Zone 53)	Northing (GDA 94 Zone 53)	MMP Reference	Date Drilled	Drilling Method*	Size of Drill Pad (m <sup>2</sup> )	No. of sumps	Status <sup>†</sup>	Rehab Date	Planned Rehab Date	Comments
EL27892	MHDDH0060	761863	7553160	Authorisation 0923-01	May 2019	RC/D	300	1	PR		Nov 2019	Shared with MHDD0058. Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0061	764929	7554057	Authorisation 0923-01	May 2019	RC	400		PR		Nov 2019	Shared with 62 and 63. Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0062	764929	7554056	Authorisation 0923-01	May 2019	RC/D	400	1	PR		Nov 2019	Shared with 62 and 63. Sumps still open (were not yet dry).
EL27892	MHDDH0063	764928	7554057	Authorisation 0923-01	May 2019	D	400	1	PR		Nov 2019	Shared with 62 and 63. Sumps still open (were not yet dry).
EL27892	MHDDH0064	764928	7554503	Authorisation 0923-01	May 2019	RC/D	300	2	PR		Nov 2019	Sumps still open (were not yet dry). Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0065	760955	7554517	Authorisation 0923-01	May 2019	RC/D	300	2	PR		Nov 2019	Sumps still open (were not yet dry). Collar still to be cut below ground. Site safe, clean and tidy.
EL27892	MHDDH0066	760902	7554505	Authorisation 0923-01	May 2019	RC/D	300	2	PR		Nov 2019	Sumps still open (were not yet dry). Collar still to be cut below ground. Site safe, clean and tidy.

\* AC = aircore/vacuum, RM = rotary mud, RC = reverse circulation, RAB = rotary air blast, D = diamond, P = percussion, V = vibracore or sonic, O = other.

† C = drillsite completely rehabilitated (hole collar removed plugged and backfilled, drill spoils buried and sample bags removed, sumps backfilled, drill pads re-contoured and ripped, photograph taken), N = no rehabilitation completed, PR = partial rehabilitation (specify remaining rehabilitation to be completed within the comments section).

**Access Track/Drill Line Rehabilitation Status**

<b>Tenement</b>	<b>Track ID</b>	<b>Tracks/lines Created (km)</b>	<b>Rehab'd tracks/lines (km)</b>	<b>Status<sup>†</sup></b>	<b>Rehab Date</b>	<b>Planned Rehab Date</b>	<b>Comments</b>
EL27892		7.65		PR			Tracks are currently being inspected and monitored and will be remediated as necessary. They will be left to revegetate and full rehabilitation will be carried out at the completion of exploration.
EL27892		0.83		PR			Tracks are currently being inspected and monitored and will be remediated as necessary. They will be left to revegetate and full rehabilitation will be carried out at the completion of exploration.
EL27892		0.065		N			Tracks will be inspected and monitored and will be remediated as necessary. They will be left to revegetate and full rehabilitation will be carried out at the completion of exploration.
EL27892		0.110		N			Tracks will be inspected and monitored and will be remediated as necessary. They will be left to revegetate and full rehabilitation will be carried out at the completion of exploration.
EL27892		0.455		N			Tracks will be inspected and monitored and will be remediated as necessary. They will be left to revegetate and full rehabilitation will be carried out at the completion of exploration.
EL27892		1.845		N			Tracks will be inspected and monitored and will be remediated as necessary. They will be left to revegetate and full rehabilitation will be carried out at the completion of exploration.

<sup>†</sup> C = rehabilitation completed, N = no rehabilitation completed, PR = partial rehabilitation (specify remaining rehabilitation to be completed within the comments section).



**Campsite Rehabilitation Status**

<b>Tenement</b>	<b>Camp Name</b>	<b>Date Est.</b>	<b>Easting (GDA 94 Zone 53)</b>	<b>Northing (GDA 94 Zone 53)</b>	<b>Camp Size (ha)</b>	<b>Status<sup>†</sup></b>	<b>Waste Removed</b>	<b>Camp Rehab Date</b>	<b>Planned Rehab Date</b>	<b>Comments</b>
EL27892	TNG and Drillers Camp	Nov 2012	765775	7552917	0.18	C	YES	Complete – October 2015		Campsite consists of the equivalent of two 30x30m sites.
EL27892	TNG and Drillers Camp	April 2017	765775	7552917	0.18	C	YES	Complete – October 2017		Campsite consists of the equivalent of two 30x30m sites.
EL27892	Drillers Camp	April 2017	765775	7552917	0.18	C	YES	Complete – December 2018		Same campsite used for every programme.
EL27892	TNG Camp	April 2017	763862	7553565	0.09	C	YES	Complete – December 2018		Same campsite used for every programme.
EL27892	Drillers Camp	April 2017	765775	7552917	0.18	C	YES	Complete – December 2018		Same campsite used for every programme.
EL27892	TNG Camp	April 2017	763862	7553565	0.09	C	YES	Complete – December 2018		Same campsite used for every programme.
EL27892	Drillers Camp	April 2017	765775	7552917	0.09	PR	YES		Nov 2019	Will also be used for planned programme and rehabbed on programme completion.
EL27892	TNG Camp	April 2017	763862	7553565	0.09	PR	YES		Nov 2019	Will also be used for planned programme and rehabbed on programme completion.

<sup>†</sup> C = rehabilitation completed, N = no rehabilitation completed, PR = partial rehabilitation (specify remaining rehabilitation to be completed within the comments section).